BX6200 S4

BX620 S4 Notes

Number	Applicable models	Cautions	Actions
H01	BX620 \$4	Some models do not support the BitLocker feature.	You can use BitLocker™ Drive Encryption on your PRIMERGY server. Before using BitLocker, please read the cautions for the BitLocker feature. >> http://www.fujitsu.com/global/services/computing/server/ia/driver/w2k8.html
H02	BX620 S4	Updating BIOS firmware or iRMC firmware will be required, depending on the models.	If you were required the updating BIOS firmware and iRMC firmware, please contact your local supplier or nearest Fujitsu sales company for details support and contact information. >> http://www.fujitsu.com/global/contact/computing/PRMRGY_index.html
H04	BX620 S4	In the case of the constitution that it is not used a built-in CD- ROM/DVD-ROM drive, the error that is not expected logging of by the event log of the OS. A source: Service Control Manager Eventlog Provider Event ID: 7026 I was not able to read the next boot start driver or a system start screwdriver: cdrom A cause Because this problem demanded start for the device driver which there is not to a computer, it occurs because a start error was recorded. There is not the evil on the system by this event log having been recorded.	It's avoidable by it set the following keys to registry, and invalidating a built-in CD- ROM/DVD-ROM drive. When it is used a built-in CD-ROM/DVD-ROM drive, this setting is unnecessary. In addition, it is necessary to put back a Registry key when it's added a built-in CD- ROM/DVD-ROM drive after this setting application. A key: HKEY_LOCAL_MACHINE¥SYSTEM¥CurrentControlSet¥Services¥cdrom The name of the value: Start The kind of the value: REG_DWORD The data of the value: 4 There is the thing that a serious problem occurs when it change registry by mistake. When it edit registry, please be careful enough. It can restore registry when I back up registry before editing in case when a problem occurred.