Notes for PRIMERGY RX600 S4

No.	Applicable models	Known issues	Workarounds
H01	RX600 S4	Some PRIMERGY models are not supporting the BitLocker feature.	You can use BitLocker™ Drive Encryption on your PRIMERGY server. Before using BitLocker, please read the cautions for the BitLocker feature. >> http://www.fujitsu.com/global/services/computing/server/ia/driver/w2k8.html
H02	RX600 S4	BIOS and iRMC firmware updates will be required, depending on your PRIMERGY models.	If you were required the updating BIOS firmware and iRMC firmware, please contact your local supplier or nearest Fujitsu sales company for details support and contact information. >> http://www.fujitsu.com/global/contact/computing/PRMRGY_index.html
H05	RX600 S4	If your server configuration is not using a parallel port and running a 32-bit operating system, an unknown error might be recorded in the OS event log. Source: Service Control Manager Eventlog Provider Event ID: 7000 The parallel port driver service failed to start due to the following error: The service cannot be started, either because it is disabled or because it has no enabled devices associated with it. Why does this happen? This event occurs when you try to boot a device driver that cannot be found in your computer. This loaged event will not cause any serious damage	Type in the following registry keys and disable the parallel port to avoid the given error. If your are using a parallel port, this setting is not required. If you add a parallel port after applying this setting, you will be required to restore the registry keys to the original settings. Registry keys: HKEY_LOCAL_MACHINE\(^2\)SYSTEM\(^2\)CurrentControlSet\(^2\)Services\(^2\) parport Value name: Start Value type: REG_DWORD Value data: 4 Changing the registry in the wrong way might generate a serious error. Special cautions are required when editing the registry. It is highly recommended to backup your registry before editing it, so that you will be able to restore the registry if any event occurs.
H06	RX600 S4	Your server might hang during an OS boot process (while the progress bar is being displayed).	Install the relevant patches, that are provided by Microsoft.

H15	RX600 S4	Your server might stop responding during anOS reboot process, and a CPU IERR error may be generated.	Please install the relevant patches provided by Microsoft. For more details, see the information provided in the Microsoft Knowledge Base (KB). If you have a software support contract, contact your support counter.
H16	RX600 S4	Your server might hang during an OS boot process.	Please install the relevant patches provided by Microsoft. For more details, see the information provided in the Microsoft Knowledge Base (KB). If you have a software support contract, contact your support counter.
H17	RX600 S4	Registry setting changes will be required in order to use the Windows Server 2008 operating system.	Type in the following registry keys: Registry keys: HKEY_LOCAL_MACHINE\(\) SYSTEM\(\) CurrentControlSet\(\) services\(\) PCI\(\) Parameters Value name: 111d\(\) 8018 Value type: REG_BINARY Value data: 00 00 10 00 00 00 00 Changing the registry in the wrong way might generate a serious error. Special cautions are required when editing the registry. It is highly recommended to backup your registry before editing it, so that you will be able to restore the registry if any event occurs