



PRIMERGY CUSTOMER INFORMATION BULLETIN

Number/Revision:

PY-CIB080-00

Issue Date:

April 08, 2022

Title:

PRIMERGY M6 models, High-speed rotation of fan when specific PCI cards are installed in PRIMERGY 2Way M6

Applies to:

Primergy
RX2530 M6
RX2540 M6

Summary:

High-speed rotation of fan when specific PCI cards are installed in PRIMERGY 2Way M6

Symptoms:

Powering on the system with a specific PCI card installed causes the system fan to rotate at high speed at all times, which increases the operating noise of the equipment.

Although the system fan is operated at high speed, there is no effect on the system operation or the life of the fan.

How to determine the issue when it occurs.

1. Check the hardware configuration whether it matches with the Occurrence Conditions.
 2. Collect the PrimeCollect to confirm the system fan is rotating in high-speed, also check there is no abnormality with the hardware.
 3. If (1) and (2) above are matched, parts replacement will not restore the device. Please inform the system administrator to apply iRMC firmware version 3.37P or later.
-



PRIMERGY CUSTOMER INFORMATION BULLETIN

(Example) RX2540 M6

System Fans (Current Speed)

When occurred (high speed rotation)

FAN 1A 1 (ok) true 13700 rpm

FAN 1B 1 (ok) true 13700 rpm

FAN 2A 1 (ok) true 13700 rpm

FAN 2B 1 (ok) true 13300 rpm

FAN 3A 1 (ok) true 13300 rpm

FAN 3B 1 (ok) true 13300 rpm

In normal status

FAN 1A 1 (ok) true 4500 rpm

FAN 1B 1 (ok) true 4500 rpm

FAN 2A 1 (ok) true 4400 rpm

FAN 2B 1 (ok) true 4400 rpm

FAN 3A 1 (ok) true 4400 rpm

FAN 3B 1 (ok) true 4400 rpm

Occurrence Conditions PRIMERGY RX2530 M6

When power is turned on with configuration with at least one PCI card and one or more other PCI devices (including OCP) in the table below, the system FAN will always rotate at high speed.

Unit	PCI card	Model
RX2530M6	PRAID EP680i FH/LP (SAS array controller card)	PY-SR4C6
		PYBSR4C6L
		PYBSR4C62L
	PRAID CP500e FH/LP (SAS array controller card)	PY-SC3FBE
		PYBSC3FBEL
	PSAS CP503i FH/LP (SAS array controller card)	PY-SC3FB
		PYBSC3FBL
		PY-SC3FBV
		PYBSC3FBVL
PYBSC3FBML		

The symptom occurs when PY-LA274U (port expansion option (1000BASE-T× 4)) is added to RX2530 M6 + PYBSR4C6L (PRAID EP680i FH/LP) configuration.



PRIMERGY CUSTOMER INFORMATION BULLETIN

Occurrence Conditions PRIMERGY RX2540 M6

Turning the power on in the configuration with the PCI card (indicated as the below table) will cause the system FAN to rotate at high speed at all times.

Unit	PCI card	Model
RX2540M6	PRAID EP680i FH/LP (SAS array controller card)	PY-SR4C6 PYBSR4C6L PYBSR4C62L
	PRAID CP500e FH/LP (SAS array controller card)	PY-SC3FBE PYBSC3FBE PYBSC3FBEL
	PSAS CP503i FH/LP (SAS array controller card)	PY-SC3FB PYBSC3FBL PY-SC3FBV PYBSC3FBVL PYBSC3FB1L PYBSC3FBML
	PLAN EP MCX4-LX 25Gb 2p SFP28 (Port expansion option)	PY-LA3F2U PYBLA3F2U PY-LA3F2UN PYBLA3F2UN
	PIB EP 100Gb 2port EDR ConnectX-6 [Dual port IB HCA card (100Gbps)]	S26361-F5724-L202 S26361-F5724-E202
	PIB EP 200Gb 2port EDR ConnectX-6 [Dual port IB HCA card (200 Gbps)]	PY-HC402 PYBHC402



PRIMERGY CUSTOMER INFORMATION BULLETIN

Cause:

PRIMERGY 2Way M6 reads PCI device information during POST and performs FAN control. If the iRMC firmware (SDR) registration is incomplete and a specific PCI device is installed in the configuration, the iRMC will recognize it as an undefined PCI card. It causes the iRMC FAN control to enter Emergency mode, which results in the system FAN rotating at high speed at all times.

Solution:

Update the server iRMC firmware to the latest version as recommended below.

RX2530 M6 : 3.37P + SDR3.32

RX2540 M6 : 3.37P + SDR3.66

Revision History:

REVISION	DATE	CHANGE SUMMARY
00	April 08, 2022	Initial draft Release based on TC23006-01
