

TX150 S6 Notes

Number	Applicable models	Cautions	Actions
H01	TX150 S6 ("PGUT1562A" or "PGUT1562B")	Some models do not support the BitLocker's features.	You can use BitLocker™ Drive Encryption on your PRIMERGY server. Before using BitLocker, please read the cautions for the BitLocker feature. >> http://www.fujitsu.com/global/services/computing/server/ia/driver/w2k8.html
H02	TX150 S6	Updating BIOS firmware or iRMC firmware will be required, depending on the models.	If you were required the updating BIOS firmware and iRMC firmware, please contact your local supplier or nearest Fujitsu sales company for details support and contact information. >> http://www.fujitsu.com/global/contact/computing/PRMRGY_index.html
H03	TX150 S6	The teaming function cannot be deployed on onboard LAN of the TX150 S6 server.	Onboard LAN on the TX150 S6 server does not support the teaming function. >> http://www.fujitsu.com/global/contact/computing/PRMRGY_index.html
H07	TX150 S6	The Hyper-V function.	The Hyper-V function is not supported.