

Number/Revision:

PY-CIB064-00

Issue Date:

March 04, 2021

Title:

ESXI 7.0 Cannot Install on BU100 - Error Connection Time Out

Applies to:

- Hardware
 - o PRIMERGY CX2550 M4
 - o PRIMERGY RX1330 M4
 - PRIMERGY RX2520 M4/M5
 - PRIMERGY RX2530 M4/M5
 - o PRIMERGY RX2540 M4/M5/M6
 - PRIMERGY RX4770 M4/M5/M6
 - PRIMERGY TX1320 M3/M4
 - PRIMERGY TX1330 M4
 - PRIMERGY TX2550 M4/M5
- Operating System
 - VMware vSphere ESXi version 7.0 or later

Effective Duration:

Permanent

Problem:

Multiple error messages are logged in dmesg and vmkernel.log every 30sec during ESXi 7.0 installation on BU100.

The issue is known by VMware: https://kb.vmware.com/s/article/81206

Cause:

Failed to make the partition by the installer of ESXi7 during installation, due to missing signal for being ready to write.



Solution:

Update the firmware for the FX3S to 0x19 on the BU100. This firmware can be downloaded from the download site: <u>https://support.ts.fujitsu.com</u>

Direct download link:

https://support.ts.fujitsu.com/IndexDownload.asp?SoftwareGuid=83644DE0-00D0-41F3-9CFA-C1CDAFB3D293

Important:

Please review the Important Information field when downloading the firmware.

Determine Installed Version: (1.7 = 0x17)

S Mass Storage								
~	. 🥑	Storage Cont	rollers					
		Status	Pro	oduct				
	۲	ОК	Dual microSD 64GB Enterprise (1	I)				
		Ports		2				
		Protocol		USB				
		Vendor		Fujitsu Limited				
		Serial Number		39B001146724AEAE1F437056041900F5				
		PCI Vendor and	d Device ID	0BF8 / 1029				
		Controller firm	ware version	1.5 (LPC), 1.7 (FX3S)				
		Alarm present		No				
		SMART Suppor	rt	Disabled				
		Correctable Err	ors	0				
		Uncorrectable	Errors	0				

Preliminary step:

Offline update tool is provided as an iso file.

You can use one of the below methods to mount/boot the iso image:

- 1. AVR (Advanced Video Redirection) session to mount iso file and boot.
- 2. CD/DVD drive.
- 3. Prepare USB pen drive (see additional information).



Update procedure: Boot the offline update tool. Press 2 to update firmware.

```
Dual microSD 64GB Enterprise Firmware Update tool V1.0L01
Firmware Package LPC_15 FX3S_19
Copyright 2021 FUJITSU LIMITED
Please select:
1: List Devices
2: Update firmware
3: Reboot system
4: Shutdown system
Select:
```

Type Yes, and press the Enter key to confirm the firmware update:



When the update has been finished successfully -> Press enter key:





Press 4 and Enter key to shut down the server:

Dual microSD 64GB Enterprise Firmware Update tool V1.0L01								
Firmware Package LPC_15 FX3S_19								
Copyright 2021 FUJITSU LIMITED								
Please select:								
1: List Devices								
2: Update firmware								
3: Reboot system								
4: Shutdown system								
Select: _								

Power on server and boot from the offline update tool again.

Press 1 and list the devices to make sure that the software version for BU100 FX3S is 0x19

```
Select: 1

PIC-File-name PIC-Status PIC-ID HW-Version SW-Version Description-name

Øxd9:1 brg01_15.hex OK Øx49 Øx0a Øx15 BU100 LPC

Øxd9:2 rai00_19.hex OK Øx4d Øx02 Øx19 BU100 FX3S

Push enter key to continue
```

Additional Information:

Prepare USB pen drive with diskpart:

Open Microsoft Windows command prompt with administrator rights and type:

- diskpart
- list disk
- select disk x (x is the usb pen drive)
- clean
- create partition primary
- select partition 1
- active
- format quick fs=fat32
- assign
- exit

Extract the iso file or mount the iso image and copy the whole content to the USB pen drive.



Revision History:

REVISION	DATE	CHANGE SUMMARY
000	March 04, 2021	Initial Release