TX120 Notes

Number	Applicable models	Cautions	Actions
H01	TX120	Some models do not support the BitLocker feature.	You can use BitLocker™ Drive Encryption on your PRIMERGY server. Before using BitLocker, please read the cautions for the BitLocker feature. >> *http://www.fujitsu.com/global/services/computing/server/ia/driver/w2k8.html*
H02	TX120	Updating BIOS firmware or iRMC firmware will be required, depending on the models.	If you were required the updating BIOS firmware and iRMC firmware, please contact your local supplier or nearest Fujitsu sales company for details support and contact information. >> *http://www.fujitsu.com/global/contact/computing/PRMRGY_index.html*
H07	TX120	The Hyper-V function.	The Hyper-V function is not supported.