

(お客様へ)

オプション製品追加搭載時の注意事項

このたびは本製品をお買い上げいただきまして、誠にありがとうございます。

本製品を追加搭載（増設）する場合は、ETERNUS DX60/DX80 のコントローラーファームウェア総合版数が以下の版数にアップデートされている必要があります。

型名			総合版数
・ ETLH6F4	・ ETLSS1HA	・ ETLSS2HA	V10L20 以上
・ ETLH8F8	・ ETLSS1MA	・ ETLSS2MA	
・ ETLH8F4	・ ETLSS1PA	・ ETLSS2PA	

作業の前にコントローラーファームウェアの総合版数をご確認いただき、適合しない場合は担当営業員または担当保守員にファームウェアアップデートをご依頼いただけますよう、お願いいたします。

なお、コントローラーファームウェア総合版数の確認方法は、『ETERNUS DX60/DX80 Web GUI ユーザーガイド』の「4.1 装置状態表示」をご参照ください。

富士通株式会社

Dear Customers,

[Attention] Optional Product Related Installation Information

Fujitsu would like to thank you for purchasing our Disk Drive Units.

When installing one of the following Disk Drive Units as an additional disk, the ETERNUS DX60/DX80 controller firmware version should be updated to **V10L20** or later.

Product Name		Version
・ ETLSS1HAU	・ ETLSS2HAU	V10L20 or later
・ ETLSS1MAU	・ ETLSS2MAU	
・ ETLSS1PAU	・ ETLSS2PAU	

Before installing any additional disk drive units, you should check your ETERNUS DX60/DX80 controller firmware version and ask your sales representative or maintenance engineer to update the firmware if necessary.

Refer to "4.1 Storage System Status" in the "ETERNUS DX60/DX80 Web GUI User Guide" for details of how to check the ETERNUS DX60/DX80 controller firmware version.

FUJITSU LIMITED