

RX100 S5 Notes

Number	Applicable models	Cautions	Actions
H01	RX100 S5	Some models do not support the BitLocker feature.	You can use BitLocker™ Drive Encryption on your PRIMERGY server. Before using BitLocker, please read the cautions for the BitLocker feature. >> http://www.fujitsu.com/global/services/computing/server/ia/driver/w2k8.html
H02	RX100 S5	Updating BIOS firmware or iRMC firmware will be required, depending on the models.	If you were required the updating BIOS firmware and iRMC firmware, please contact your local supplier or nearest Fujitsu sales company for details support and contact information. >> http://www.fujitsu.com/global/contact/computing/PRMRGY_index.html
H07	RX100 S5	"Hyper-V" function.	"Hyper-V" function has not been supported as of July, 2008.