

TX300 S4 Notes

Number	Applicable models	Cautions	Actions
H01	TX300 S4	Some models do not support the BitLocker feature.	You can use BitLocker™ Drive Encryption on your PRIMERGY server. Before using BitLocker, please read the cautions for the BitLocker feature. >> http://www.fujitsu.com/global/services/computing/server/ia/driver/w2k8.html
H02	TX300 S4	Updating BIOS firmware or iRMC firmware will be required, depending on the models.	If you were required the updating BIOS firmware and iRMC firmware, please contact your local supplier or nearest Fujitsu sales company for details support and contact information. >> http://www.fujitsu.com/global/contact/computing/PRMRGY_index.html
H06	TX300 S4	It is likely to hang up because of the progress bar display OS's starting.	Microsoft is preparing the update module.
H07	TX300 S4	The Hyper-V function.	The Hyper-V function is not supported.