



Unnecessary commands are showed by underline, and incorrect commands are showed by tracing with black and white characters.

2. Power ON

- 1) Start the "Special Mode"
- 2) Select "Command Trace"



After selecting command trace, please print the data by the printing program.
The following data is showed to inform the unnecessary or incorrect commands.



*Example