

Intel Firmware Vulnerability

List of affected FUJITSU Products

In an advisory note on May 1 2017, Intel published security information about an escalation of privilege vulnerability in Intel® Active Management Technology (AMT), Intel® Standard Manageability (ISM), and Intel® Small Business Technology. Reference: INTEL-SA-00075 or CVE-2017-5689

Last revised: 24 May 2017

Notes

- This list provides an overview of Fujitsu affected systems introduced since 2012.
- The vulnerability currently affects CCD products only.
- The list is regularly updated.

Desktop PC (ESPRIMO)

Affected model	New Firmware (w fix)	Firmware Release date	New BIOS (w fix)	BIOS release date
ESPRIMO P9900	6.2.61.3535	ww23	not planned	not planned
ESPRIMO E9900	6.2.61.3535	ww23	not planned	not planned
ESPRIMO C5731	6.2.61.3535	ww24	not planned	not planned
ESPRIMO P5731/P7936	7.1.91.3272	ww21	not planned	not planned
ESPRIMO E5731	6.2.61.3535	ww24	not planned	not planned
ESPRIMO E7936	6.2.61.3535	ww24	not planned	not planned
ESPRIMO E3521/P2560	6.2.61.3535	ww24	not planned	not planned
ESPRIMO E700/P700	7.1.91.3272	ww21	not planned	not planned
ESPRIMO E900/P900	7.1.91.3272	ww21	not planned	not planned
ESPRIMO C700	7.1.91.3272	ww21	not planned	not planned
ESPRIMO E710/P710	8.1.71.3608	May 19, 2017	not planned	not planned
ESPRIMO E910/P910	8.1.71.3608	May 19, 2017	not planned	not planned
ESPRIMO Q910	8.1.71.3608	May 19, 2017	not planned	not planned
ESPRIMO C710/C910-L	8.1.71.3608	May 19, 2017	not planned	not planned
ESPRIMO X913/X913T	8.1.71.3608	May 19, 2017	not planned	not planned
ESPRIMO E720/P720	9.1.41.3024	May 08, 2017	not planned	not planned
ESPRIMO E920/P920/PH521	9.1.41.3024	May 08, 2017	not planned	not planned
ESPRIMO C720/Team PoS 7000S	9.1.41.3024	May 08, 2017	not planned	not planned
ESPRIMO X923/ESPRIMO X923-T	9.1.41.3024	May 08, 2017	not planned	not planned
ESPRIMO E520/ESPRIMO P520	9.1.41.3024	May 08, 2017	not planned	not planned
ESPRIMO Q920	9.1.41.3024	May 08, 2017	not planned	not planned
ESPRIMO Q920	9.1.41.3024	May 08, 2017	not planned	not planned
ESPRIMO P756	11.0.25.3001	May 04, 2017	R1.21.0	ww24
ESPRIMO P956	11.0.25.3001	May 04, 2017	R1.21.0	ww24
ESPRIMO Q956	11.0.25.3001	May 04, 2017	R1.21.0	ww23
CELSIUS W550, W550 POWER	11.0.25.3001	May 04, 2017	R1.21.0	ww23
ESPRIMO D756 (E85+;E90+;E94+)	11.0.25.3001	May 04, 2017	R1.21.0	ww23
ESPRIMO D956 (E85+;E90+;E94+;LL)	11.0.25.3001	May 04, 2017	R1.21.0	ww23
ESPRIMO X956	11.0.25.3001	May 04, 2017	R1.21.0	ww24
ESPRIMO P757 (E85+;E90+;E94+)	11.6.27.3264	May 04, 2017	R1.8.0	ww22
ESPRIMO P957 (E85+;E90+;E94+;POWER)	11.6.27.3264	May 04, 2017	R1.8.0	ww22

ESPRIMO Q957, MRE	11.6.27.3264	May 04, 2017	R1.8.0	ww22
ESPRIMO D757 (E85+;E90+;E94+)	11.6.27.3264	May 04, 2017	R1.8.0	ww22
ESPRIMO D957 (E85+;E90+;E94+)	11.6.27.3264	May 04, 2017	R1.8.0	ww22
ESPRIMO D582(/G, /F, /FX, /E, /EW, /EX)	not planned	not planned	TBD	End of June

Workstation (CELSIUS)

Affected model	New Firmware (w fix)	Firmware Release date	New BIOS (w fix)	BIOS release date
CELSIUS W280	6.2.61.3535	ww23	not planned	not planned
CELSIUS W380/W480	6.2.61.3535	ww23	not planned	not planned
CELSIUS W410	7.1.91.3272	ww21	not planned	not planned
CELSIUS W510	7.1.91.3272	ww21	not planned	not planned
CELSIUS R920/R920 Power	7.1.91.3272	ww22	not planned	not planned
CELSIUS R930/R930 Power	7.1.91.3272	May 19, 2017	not planned	not planned
CELSIUS M720/M720 Power	7.1.91.3272	ww22	not planned	not planned
CELSIUS M730/M730 Power	7.1.91.3272	May 19, 2017	not planned	not planned
CELSIUS W420	8.1.71.3608	May 19, 2017	not planned	not planned
CELSIUS W520	8.1.71.3608	May 19, 2017	not planned	not planned
CELSIUS C620	8.1.71.3608	May 19, 2017	not planned	not planned
CELSIUS W530	9.1.41.3024	May 08, 2017	not planned	not planned
CELSIUS M740/M740 Power	9.1.41.3024	May 09, 2017	not planned	not planned
CELSIUS R940/R940 Power	9.1.41.3024	May 09, 2017	not planned	not planned
CELSIUS W550	11.0.25.3001	May 04, 2017	R1.21.0	ww23
CELSIUS J550	11.0.25.3001	May 04, 2017	R1.21.0	ww23
CELSIUS J550/2	11.6.27.3264	May 04, 2017	R1.8.0	ww22
CELSIUS W570, POWER, POWER+	11.6.27.3264	May 04, 2017	R1.8.0	ww22

Mobile (LIFEBOOK/STYLISTIC/CELSIUS)

Affected model	New Firmware (w fix)	Firmware Release date
LIFEBOOK T730	V1.09	Mid of June
LIFEBOOK E780	V1.21	Mid of June
LIFEBOOK E780; CELSIUS H700	V1.21	Mid of June
LIFEBOOK S760	V1.22	Mid of June
LIFEBOOK P770	V1.17	Mid of June
LIFEBOOK S710	V1.12	Mid of June
LIFEBOOK T900; LIFEBOOK T900/B	V1.20	Mid of June
LIFEBOOK T731	V1.11	Mid of June
LIFEBOOK T731/D	V1.03	Mid of June
LIFEBOOK E741/C; LIFEBOOK E741/D	V1.12	Mid of June
LIFEBOOK E751; LIFEBOOK E781; LIFEBOOK S751; LIFEBOOK S781	V1.23	Mid of June
LIFEBOOK S761; LIFEBOOK S561	V1.21	Mid of June
LIFEBOOK NH90/DN; CELSIUS H910	V1.17	Mid of June
CELSIUS H710	V1.18	Mid of June
LIFEBOOK P771	V1.18	Mid of June
LIFEBOOK T901 (Intel Graphics model)	V1.18	Mid of June
LIFEBOOK T901 (NVIDIA Graphics model)	V1.09	Mid of June
LIFEBOOK A743/G; LIFEBOOK A743/GW	V1.17	Early of June
LIFEBOOK E742/E	V1.08	Early of June
LIFEBOOK E742/F; LIFEBOOK E742/FW	V2.08	Early of June
LIFEBOOK E752; LIFEBOOK E782; LIFEBOOK S752; LIFEBOOK S782	V1.17	Early of June
LIFEBOOK E752; LIFEBOOK E782; LIFEBOOK S752; LIFEBOOK S782; (Windows 8 model)	V2.15	Early of June
LIFEBOOK S762	V1.12	Early of June
LIFEBOOK S762 (Windows 8 model)	V2.13	Early of June
LIFEBOOK E733; LIFEBOOK E743; LIFEBOOK E753	V1.10	Early of June



CELSIUS H720	V1.09	Early of June
CELSIUS H720 (Windows 8 model)	V2.13	Early of June
CELSIUS H920	V1.04	Early of June
CELSIUS H920 (Windows 8 model)	V2.08	Early of June
LIFEBOOK P772	V1.13	Early of June
LIFEBOOK P772 (Windows 8 model)	V2.12	Early of June
LIFEBOOK U772	V1.10	Early of June
LIFEBOOK U772 (Windows 8 model)	V2.11	Early of June
STYLISTIC Q702	V2.21	Early of June
LIFEBOOK T902	V1.05	Early of June
LIFEBOOK T902 (Windows 8 model)	V2.12	Early of June
LIFEBOOK T732	V1.10	Early of June
LIFEBOOK E754; LIFEBOOK E744; LIFEBOOK E734	V1.30	End of May
LIFEBOOK S904	V1.24	End of May
CELSIUS H730	V1.17	End of May
LIFEBOOK U904/H; LIFEBOOK U904	V1.15	End of May
STYLISTIC Q704	V1.37	End of May
LIFEBOOK T734	V1.13	End of May
LIFEBOOK T904	V1.16	End of May
LIFEBOOK S935	V1.15	Mid of June
STYLISTIC Q775	V1.17	Mid of June
LIFEBOOK T725	V1.17	Mid of June
LIFEBOOK T935	V1.17	Mid of June
LIFEBOOK U745	V1.19	Mid of June
STYLISTIC Q665	V1.12	Mid of June
LIFEBOOK E556; LIFEBOOK E546	V1.16	May 24, 2017
LIFEBOOK E756; LIFEBOOK E746; LIFEBOOK E736	V1.19	May 24, 2017
LIFEBOOK S936	V1.15	May 24, 2017
CELSIUS H760	V1.19	May 24, 2017
STYLISTIC Q736	V1.12	May 24, 2017
LIFEBOOK T726	V1.13	May 24, 2017
LIFEBOOK T936	V1.12	May 24, 2017
STYLISTIC Q616	V1.09	May 24, 2017
STYLISTIC R726	V1.14	Mid of June
LIFEBOOK E557; LIFEBOOK E547	V1.11	May 24, 2017
LIFEBOOK S937	V1.05	May 24, 2017
LIFEBOOK U937	V1.07	May 24, 2017
LIFEBOOK P727	V1.09	May 24, 2017
STYLISTIC Q737	V1.09	May 24, 2017
LIFEBOOK T937	V1.09	May 24, 2017
LIFEBOOK U727; LIFEBOOK U757; LIFEBOOK U747	V1.14	May 24, 2017
STYLISTIC R727	V1.10	Mid of June
CELSIUS H970	V1.07	End of May

Contact Us

HONG KONG

Fujitsu PC Asia Pacific Ltd
Tel: (852) 3910-8228
Email: fpca.hksales@hk.fujitsu.com
hk.fujitsu.com/pc

PHILIPPINES

Fujitsu Philippines, Inc.
Tel: (63) 2-812-4001
Email: info@ph.fujitsu.com
ph.fujitsu.com/pc

VIETNAM

Fujitsu Vietnam Limited (Hanoi)
Tel: (84) 4-2220-3113
Email: sales@vn.fujitsu.com
vn.fujitsu.com/pc

SINGAPORE

Fujitsu Asia Pte Ltd.
Tel: (65) 6710-5403
E mail: fsg.info.pc@sg.fujitsu.com
sg.fujitsu.com/pc

PHILIPPINES

Fujitsu (Malaysia) Sdn. Bhd
Tel: (60) 3-8318-3700
Email: marketing@my.fujitsu.com
my.fujitsu.com/pc

CHINA

Fujitsu (China) Co., Ltd.
Tel: (86) 021-26079126
Email: cpcacn.support@cn.fujitsu.com
cn.fujitsu.com/pc

TAIWAN

Fujitsu Taiwan Ltd.
Tel: (886) 0800-688-028
Email: lifebook@tw.fujitsu.com
tw.fujitsu.com/pc

INDONESIA

Pt. Fujitsu Indonesia
Tel: (62) 21-570-9330
Email: callcenter@id.fujitsu.com
id.fujitsu.com/pc

THAILAND

Fujitsu (Thailand) Co., Ltd
Tel: (66) 0-2302-1500
Email: info@th.fujitsu.com
th.fujitsu.com/pc

Note: For countries not listed above, please contact our Hong Kong office.