



Service Facts

UEFI-BIOS bug

Affected and unaffected products

Table of Contents

1. CLIENT COMPUTING DEVICES.....	2
2. SERVER PRODUCTS	4
3. STORAGE PRODUCTS	7
4. SOLUTIONS.....	7
5. ENTERPRISE SERVER.....	7

Disclaimer

This Document is provided on an as-is basis solely for informational purposes and does not imply any kind of guaranty or warranty, including the warranties of merchantability or fitness for a particular purpose. Your use of the information contained herein is at your own risk. All information provided herein is based on FUJITSU's current knowledge and understanding of the vulnerability and impact to FUJITSU Hardware and Software products.

FUJITSU reserves the right to change or update this document at any time.

1. CLIENT COMPUTING DEVICES

UNAFFECTED:

Product	Issue date	Comment
CELVIN NAS (Q600, Q700, Q800, Q802, Q902, QR802, Q703)	2014-10-27	
OEM-Mainboard D3348-B1	2014-10-27	
CELSIUS M740	2014-10-27	
CELSIUS R940	2014-10-27	
STYLISTIC Q572	2014-11-04	
STYLISTIC Q584	2014-11-04	

AFFECTED:

Product	Issue date	Comment
CELSIUS H730	2014-11-06	Patch release is scheduled for CW47/2014.
CELSIUS W530	2014-11-03	BIOS Version 1.31.0 or above are available under http://www.fujitsu.com/de/support/
ESPRIMO A525-L	2014-11-03	Patch release is scheduled for CW46/2014.
ESPRIMO C720	2014-11-03	BIOS Version 1.30.0 or above are available under http://www.fujitsu.com/de/support/
ESPRIMO E420 /E420 D / P420	2014-11-03	BIOS Version 1.30.0 or above are available under http://www.fujitsu.com/de/support/
ESPRIMO E520 / P520	2014-11-03	BIOS Version 1.30.0 or above are available under http://www.fujitsu.com/de/support/
ESPRIMO E720 / P720	2014-11-03	BIOS Version 1.30.0 or above are available under http://www.fujitsu.com/de/support/
ESPRIMO E920 / ESPRIMO P920	2014-11-03	BIOS Version 1.30.0 or above are available under http://www.fujitsu.com/de/support/
ESPRIMO PH320	2014-11-03	BIOS Version 1.30.0 or above are available under http://www.fujitsu.com/de/support/
ESPRIMO Q520 / Q920	2014-11-03	BIOS Version 1.31.0 or above are available under http://www.fujitsu.com/de/support/

ESPRIMO X923 / X923-T	2014-11-03	BIOS Version 1.30.0 or above are available under http://www.fujitsu.com/de/support/
FUTRO S520	2014-11-03	Patch release is scheduled for CW46/2014
FUTRO S720	2014-11-03	Patch release is scheduled for CW46/2014
FUTRO S920	2014-11-03	Patch release is scheduled for CW46/2014
FUTRO X923 / FUTRO X923-T	2014-11-03	Patch release is scheduled for CW46/2014
LIFEBOOK E733	2014-11-06	Patch release is scheduled for CW47/2014
LIFEBOOK E743	2014-11-06	Patch release is scheduled for CW47/2014
LIFEBOOK E753	2014-11-06	Patch release is scheduled for CW47/2014
LIFEBOOK U772	2014-11-06	Patch release is scheduled for CW48/2014
OEM-Mainboard D3313-S1 / S2 / S3	2014-11-03	Patch release is scheduled for CW46/2014
OEM-Mainboard D3220-A1 / B1	2014-11-03	BIOS Version 1.30.0 or above are available under http://www.fujitsu.com/de/support/
OEM-Mainboard D3221-A1 / B1	2014-11-03	BIOS Version 1.30.0 or above are available under http://www.fujitsu.com/de/support/
OEM-Mainboard D3222-A1 / B1	2014-11-03	BIOS Version 1.30.0 or above are available under http://www.fujitsu.com/de/support/
OEM-Mainboard D3230-A1 / B1	2014-11-03	BIOS Version 1.30.0 or above are available under http://www.fujitsu.com/de/support/
OEM-Mainboard D3240-B1	2014-11-03	BIOS Version 1.30.0 or above are available under http://www.fujitsu.com/de/support/
STYLISTIC Q702	2014-11-06	Patch release is scheduled for CW48/2014
STYLISTIC Q704	2014-11-06	Patch release is scheduled for CW46/2014

2. SERVER PRODUCTS

UNAFFECTED:

Product	Issue date	Comment
PRIMERGY BX400 S1 / BX900 S2 / BX900 MMB S1	2014-10-27	
PRIMERGY BX92x S1/S2	2014-10-27	
PRIMERGY BX600 S3, BX620 S4 / S5 / S6 BX630S2	2014-10-27	
PRIMERGY SX650, SX910, SX940, SX960, SX980 S1 / S2	2014-10-27	
PRIMERGY CX250 S1, CX270 S1, CX400 S1	2014-10-27	
PRIMERGY CX420 S1 CX272 S1	2014-10-27	
PRIMERGY CX1000, CX120, CX122	2014-10-27	
PRIMERGY RX100 / S2 / S3 / S4 / S5 / S6 S7p / S7	2014-10-27	
PRIMERGY RX200 / S2 / S3 / S4 / S5 / S6	2014-10-27	
PRIMERGY RX300 / S2 / S3 / S4 / S5 / S6	2014-10-27	
PRIMERGY RX500 S7	2014-10-27	
PRIMERGY RX900 S1 / S2	2014-10-27	
PRIMERGY RX2540 M1	2014-10-27	
PRIMERGY SX05, SX10 S2	2014-10-27	
PRIMERGY TX100 S1 / S2 / S3 / S3p	2014-10-27	
PRIMERGY TX120 S2 / S3 / S3p	2014-10-27	
PRIMERGY TX140 S1 / S1p	2014-10-27	
PRIMERGY TX150 S6 / S7	2014-10-27	
PRIMERGY TX200 S4 / S5 / S6	2014-10-27	
PRIMERGY TX300 S4 / S5 / S6	2014-10-27	

PRIMEQUEST 1800 E	2014-10-27	
PRIMEQUEST 2400 E / 2800 B/E	2014-10-27	

AFFECTED:

Please note: all PRIMERGY Servers are delivered with the default "Legacy Boot" mode for BIOS switch. If default settings are kept, servers are not affected. However, for maximum security, Fujitsu recommends to install a patch for the following products:

Product	Issue date	Comment
PRIMERGY BX924 S4	2014-11-17	Patch release is scheduled for CW 48/2014
PRIMERGY RX100 S8	2014-11-05	BIOS release 2.10.0 is available under http://www.fujitsu.com/de/support/
PRIMERGY RX300 S7	2014-11-17	BIOS release 1.29.0 is available under http://www.fujitsu.com/de/support/
PRIMERGY RX300 S8	2014-11-05	BIOS release 1.14.0 is available under http://www.fujitsu.com/de/support/
PRIMERGY RX350 S7	2014-11-17	BIOS release 1.29.0 is available under http://www.fujitsu.com/de/support/
PRIMERGY RX350 S8	2014-11-05	BIOS release 1.14.0 is available under http://www.fujitsu.com/de/support/
PRIMERGY RX1330 M1	2014-11-05	BIOS release 2.10.0 is available under http://www.fujitsu.com/de/support/
PRIMERGY RX2520 M1	2014-11-05	BIOS release 1.14.0 is available under http://www.fujitsu.com/de/support/
PRIMERGY SX350 S8	2014-11-05	BIOS release 1.14.0 is available under http://www.fujitsu.com/de/support/
PRIMERGY TX140 S2	2014-11-05	BIOS release 1.14.0 is available under http://www.fujitsu.com/de/support/
PRIMERGY TX300 S7	2014-11-17	BIOS release 1.29.0 is available under http://www.fujitsu.com/de/support/

PRIMERGY TX300 S8	2014-11-05	BIOS release 1.14.0 is available under http://www.fujitsu.com/de/support/
PRIMERGY TX1310 M1	2014-10-05	BIOS release 1.4.0 is available under http://www.fujitsu.com/de/support/
PRIMERGY TX1320 M1	2014-10-05	BIOS release 2.10.0 is available under http://www.fujitsu.com/de/support/
PRIMERGY TX1330 M1	2014-10-05	BIOS release 2.10.0 is available under http://www.fujitsu.com/de/support/
PRIMERGY TX2540 M1	2014-11-05	BIOS release 1.14.0 is available under http://www.fujitsu.com/de/support/

3. STORAGE PRODUCTS

UNAFFECTED:

Product	Issue date	Comment
ETERNUS CD10000	2014-10-27	
ETERNUS CS800	2014-10-28	
ETERNUS CS8000	2014-10-29	
ETERNUS DX Series	2014-10-24	
ETERNUS LT20 – LT60 S1/S2	2014-10-28	
ETERNUS LT260	2014-10-28	
FibreCAT SX60 - 100	2014-11-11	
Support Gateway (ACA)	2014-10-29	

4. SOLUTIONS

UNAFFECTED:

Product	Issue date	Comment
FLEXFRAME for SAP	2014-10-27	Underlying PRIMERGY systems should be checked
HANA	2014-10-27	Underlying PRIMERGY systems should be checked

5. ENTERPRISE SERVER

UNAFFECTED:

Product	Issue date	Comment
BS2000 S-Series	2014-10-27	
BS2000 SQ-Series	2014-10-29	
BS2000 SX-Series	2014-10-27	

Service Facts UEFI-BIOS bug
Date: November 18, 2014
Version: 1.3